

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India) ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax : +91 (0265) 2638382. E-mail : erda@erda.org

Web : http://www.erda.org



TEST REPORT

SHEET: 1 OF 4

MRM PROCOM PVT. LTD. Plot No. 20-21, Industrial Estate, Sector-59, Phase-II, Faridabad-121004, Haryana.		TEST REPORT NO. : RP-1516-015946 DATE : 27.07.2015	
		CUSTOMER REF. NO. :	DATE: 07.07.2015 DATE OF TESTING 09.07.2015 to 22.07.2015
		DATE OF SAMPLE RECEIPT	
		08.07.2015	
SAMPLE DESCRIPTION		SAMPLE IDENTIFICATION	
CURRENT TRANSFORMER		SR. NO. : 2015070412	
MFD. BY	: MRM PROCOM PVT. LTD.		
RATIO	: 1000/5 A	ERDA-00098795	
BURDEN	: 15 VA		
CLASS	: 0.5	DRAWING NO.: MRM/CT/1000-5-0.5/0715/05 REV® SHEET NO. 05	
H.S.V./I.L.	: 0.66/3 kV		
FREQUENCY	: 50 Hz.		
Insulation Cla	ss : E	ENCLOSURE:	10. 300 HANDE
TYPE	: RC/BPL	Annexure-I (As per sheet 1 of 1)	

TEST DETAILS & TEST SPECIFICATION ARE AS PER SHEET NO. 2 OF 4.

TEST RESULTS: As per sheet: 3 of 4 to 4 of 4.

REMARKS: The sample **conforms** to the requirements of the mentioned

standard as mentioned in tests no. 1 to 6 on sheet no. : 2 of 4.

PREPARED BY

thazawa

CHECKED BY

APPROVED BY (S.B.PATEL)

Note: 1. This report relates only to the particular sample received in good condition for testing at ERDA.

2. This report cannot be reproduced in part under any circumstances.

3. Publication of this report requires prior permission in writing from Director, ERDA.

4. Only tests asked for by the customer have been carried out.

In case of any dispute, Vadodara will be the exclusive jurisdiction & shall be construed as where the cause has arised.

Caution: ERDA is not responsible for the authenticity of photocopied or reproduced test reports. ERDA provides support to customers for verification of the authenticity of test reports issued by ERDA.





(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India) ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax : +91 (0265) 2638382 E-mail : erda@erda.org

Web : http://www.erda.org -





SHEET: 2 OF 4

TEST REPORT NO.: RP-1516-015946

DATE : 27.07.2015

TEST DETAILS & TEST SPECIFICATION:

Sr.	TESTS	REFERENCE STANDARD		
No.				
1.	Verification of terminal marking and polarity.	Cl. No. 9.2 of IS 2705 (Part 1): 1992		
2.	Power frequency dry withstand test on primary winding.	Cl. No. 9.3 of IS 2705 (Part 1): 1992		
3.	Power frequency dry withstand test on secondary winding.	Cl. No. 9.4 of IS 2705 (Part 1): 1992		
4.	Over voltage inter-turn test.	Cl. No. 9.5 of IS 2705 (Part 1): 1992		
5.	Determination of errors according to the requirements of the appropriate accuracy class.	Cl. No. 7.2.1 of IS 2705 (Part 2): 1992		
6.	Temperature rise test.	Cl. No. 9.7 of IS 2705 (Part 1): 1992		

PREPARED BY

CHECKED BY





(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India) ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax ; +91 (0265) 2638382

E-mail : erda@erda.org
Web : http://www.erda.org



SHEET: 3 OF 4

TEST REPORT NO.: RP-1516-015946

DATE

: 27.07.2015

TEST RESULTS:

1. Verification of terminal marking and polarity.

(Cl. No. 9.2 of IS 2705 (Part 1): 1992)

Primary winding terminals

: P1-P2

Secondary windings terminals: S1-S2

Terminal marking & polarity was found Ok.

Terminal marking was found marked clearly & Indelibly.

REMARK: Conforms

2. Power frequency dry withstand test on primary winding.

(Cl. No. 9.3 of IS 2705 (Part 1): 1992)

The power frequency voltage of 3 kV rms was applied between the primary winding terminals and earth for one minute duration. The secondary windings terminals were connected together to earth.

The sample withstood the test voltage without any disruptive discharge.

REMARK: Conforms

3. Power frequency dry withstand test on secondary winding. (Cl. No. 9.4 of IS 2705 (Part 1): 1992)

The power frequency voltage of 3 kV (rms) was applied between the secondary windings terminals (all) connected together and the earth. The primary winding terminals were shorted and connected to the earth. The test voltage was applied for one minute. There was no disruptive discharge observed.

The sample withstood the test voltage satisfactorily.

REMARK: Conforms

4. Over voltage inter-turn test. (Cl. No. 9.5 of IS 2705 (Part 1): 1992)

With the primary winding open circuited, a voltage at rated frequency was applied to the secondary winding terminals (S1-S2) such as to produce a secondary limiting current of rms value equals to rated secondary current (i.e. 5 amp.) for one minute.

The sample withstood the applied voltage satisfactorily for one minute.

REMARK: Conforms

PREPARED BY

CHECKED BY

1753120



(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India) ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax : +91 (0265) 2638382 E-mail : erda@erda.org

Web : http://www.erda.org -





SHEET: 4 OF 4

TEST REPORT NO.: RP-1516-015946

MANAGEMENT CONTRACTOR OF THE PROPERTY OF THE P

DATE : 27.07.2015

Determination of errors according to the requirements of the appropriate accuracy class. (Cl. No. 7.2.1 of IS 2705 (Part 2): 1992)

PHASE ANGLE	RATIO ERROR	% OF RATED	RATIO ERROR	PHASE ANGLE
ERROR IN MIN.	IN %	CURRENT	IN %	ERROR IN MIN.

RATIO: 1000/5 A, BURDEN: 15 VA, CLASS: 0.5

BURDEN: 100 %	at 0.8 Lag. P. F.		BURDEN: 25	% at U. P. F.
6.45	-0.110	120	0.163	6.89
5.38	-0.099	100	0.147	9.48
10.33	-0.248	20	0.122	12.86
19.45	-0.510	5	0.040	21.59

REMARK: Conforms

6. Temperature rise test. (Cl. No. 9.7 of IS 2705 (Part 1): 1992)

A Continuous rated thermal current equals to 120% (i. e. 1000 A*1.2=1200 A) of the primary current at rated frequency was circulated in the primary winding of the CT. Rated burden (i.e. 15 VA) was connected to the secondary winding terminals (i.e., S1-S2) of the CT. At steady state, temperature of the body and ambient temperature were recorded. The resistances of secondary winding were measured immediately after shut down and temperature rise calculated.

The temperature rises so obtained were as follows:

Sr. no.	Temperature rise of :	Specified limit for temperature rise test.	Obtained value :
1.	Secondary winding (Resistance method)	70 °C	S1-S2: 34.9 °C
2.	Body (Thermocouple method)	70 °C	31.5 °C
3.	Ambient temperature	40 °C	31.0 °C

REMARK: Conforms

PREPARED BY

CHECKED BY





(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India) ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax : +91 (0265) 2638382 E-mail : erda@erda.org

Web : http://www.erda.org





Annexure-I

TEST REPORT NO.: RP-1516-015946

DATE : 27.07.2015

SHEET: 1 OF 1

PHOTOGRAPHS OF TEST SAMPLE













